

## **APPENDIX C**

---

### **Site Photographs - Excavation**



8/3/06 – Excavation of Maintenance Area soil, looking north.




8/1/06 – Deep Compressor Area excavation, looking southeast. Note green coloration in surface soil.



8/9/06 – Excavation of Compressor Area, looking northeast.



8/7/06 – Deep Compressor Area excavation, looking north. Note seep in northwest corner and concrete vault at east of excavation.



8/8/06 – Deep Compressor Area excavation, northwest corner. Note seep emanating from ~4 feet bgs.



8/9/06 – Deep Compressor Area excavation, looking east. Note groundwater at base of excavation.



8/9/06 – Deep Compressor Area excavation, looking south. Note concrete cistern in left background.



8/10/06 – Deep Compressor Area excavation, looking north from Maintenance Area.





8/10/06 – Deep Compressor Area excavation looking north, after excavation and sampling. Note groundwater.



8/10/06 – Maintenance Area excavation, looking east after confirmation sampling. Note red sample location flags. Toluene affected soil stockpile in background left in the East Parcel.



8/9/06 – Confirmation sampling. Note bucket for composite sample in foreground.



8/10/06 – Compressor Area excavation, looking south from south Sulfuric Acid Area. Note staked as-built corners of excavation, and red sample location flags.




8/10/06 – South Sulfuric Acid Area after excavation and sampling, looking southwest.



8/3/06 – Asbestos-containing pipe (sample PIPE-1) in north Maintenance Area (pipe is central left side of photo).



8/10/06 – GPS and level surveying, after excavation and sampling. Note red sample flags in excavations. Photo taken from north Sulfuric Acid Area, looking south.



8/7/06 – Close-up of asbestos-containing pipe (PIPE-1) in north Maintenance Area.





8/9/06 – Asbestos-containing pipe in west Maintenance Area (sample PIPE-2) (asbestos is lining inside of pipe).



8/8/06 – Oil-water separator at south of Maintenance Area, looking southwest.



8/9/06 – Long Services asbestos abatement of loose asbestos pipe (PIPE-1).



8/8/06 – Inside of oil-water separator prior to pumping out.



8/9/06 – Oil-water separator after pump out of liquid and placement of absorbent.



8/10/06 – Covered toluene-affected soil stockpile on East Parcel from Deep Compressor Area excavation.



8/3/06 – West Parcel, looking southwest. Note stockpiles of excavated East Parcel soil in background within the barrier wall.



8/28/06 – Maintenance Area deep excavation, looking northwest (low tide).



8/30/06 – Maintenance Area deep excavation,  
looking south (high tide).



8/30/06 – Maintenance Area deep excavation,  
looking west during dewatering.





9/23/06 – View of south side of Maintenance Area excavation showing extent of excavation prior to removal of trees and excavation to the southern fenceline.



9/23/06 – Close-up of southwest Maintenance Area excavation showing darker soil at depth, and groundwater seeping into excavation. Note fencepost dangling in air along the southern side of the excavation.



9/23/06 – View looking east along southern side of southwest Maintenance Area excavation showing sidewall and dangling fenceposts.